

## United States Patent and Trademark Office

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OFFICE
WASHINGTON, D.C. 20 231
WWW.uspta.gov

#### \*BIBDATASHEET\*

CONFIRMATION NO. 4795

Bib Data Sheet									
SERIAL NUME 10/067,135	RULE		CLASS 239		GROUP ART UNIT 3752			ATTORNEY DOCKET NO. 12929.1070US01	
APPLICANTS  Robb Edward Bennett, New Prague, MN;  Gary Lee Butler, Silver Lake, MN;  Thomas J. Bachinski, Lakeville, MN;David J. Oja, Burnsville, MN;									
** CONTINUING DATA **********************************									
F REQUIRED, FOREIGN FILING LICENSE GRANTED ** 03/14/2002									
Foreign Priority claimed				STATE OR COUNTRY MN		DRAWING CL		AL MS	INDEPENDENT CLAIMS 8
ADDRESS MERCHANT & GOULD P.C. P.O. Box 2903 Minneapolis , MN 55402-0903									
Apparatus for generating a flame out of a liquid									
RECEIVED	No to charge/credit DEPOSIT ACCOUNT					All Fees  1.16 Fees (Filing)  1.17 Fees (Processing Ext. of time)  1.18 Fees (Issue)			
1768					Other				

# This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

OTHER:

### IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.